

## *Final report RM 2018:03e*

**Serious incident involving a near collision on 25 May 2017 between Swedish and French fighter aircraft during the international military exercise ACE 17 in the air-space north-west of Arvidsjaur, Norrbotten County.**

File no. M-14/17

16 March 2018

SHK investigates accidents and incidents from a safety perspective. Its investigations are aimed at preventing a similar event from occurring in the future, or limiting the effects of such an event. The investigations do not deal with issues of guilt, blame or liability for damages.

The report is also available on SHK's web site: [www.havkom.se](http://www.havkom.se)

ISSN 1400-5719

This document is a translation of the original Swedish report. In case of discrepancies between this translation and the Swedish original text, the Swedish text shall prevail in the interpretation of the report.

Photos and graphics in this report are protected by copyright. Unless otherwise noted, SHK is the owner of the intellectual property rights.

With the exception of the SHK logo, and photos and graphics to which a third party holds copyright, this publication is licensed under a Creative Commons Attribution 2.5 Sweden license. This means that it is allowed to copy, distribute and adapt this publication provided that you attribute the work.

The SHK preference is that you attribute this publication using the following wording: "Source: Swedish Accident Investigation Authority".



Where it is noted in the report that a third party holds copyright to photos, graphics or other material, that party's consent is needed for reuse of the material.

Cover photo no. 3 - © Anders Sjödén/Swedish Armed Forces.

## Content

General observations and delimitations .....	5
The investigation .....	6
SUMMARY .....	12
1. FACTUAL INFORMATION .....	14
1.1 History of the flight.....	14
1.1.1 Preconditions .....	14
1.1.2 Sequence of events .....	19
1.1.3 The sequence of events from the perspective of HAMMER (the Gripen group) .....	23
1.1.4 The sequence of events from the perspective of GUSTO (the Mirage two-ship) .....	26
1.1.5 The sequence of events from the perspective of the tactical control ...	29
1.1.6 The sequence of events from the perspective of the Mission Commander .....	30
1.2 Injuries to persons.....	31
1.3 Damage to aircraft.....	31
1.4 Other damage.....	31
1.5 Personnel information.....	31
1.5.1 Qualifications and duty time of the pilots .....	31
1.5.2 Passengers.....	31
1.5.3 Other personnel .....	32
1.6 Aircraft information.....	32
1.6.1 Aircraft A – Gripen general.....	32
1.6.2 Aircraft B – Mirage 2000 general.....	33
1.6.3 Description of parts or systems related to the occurrence (Gripen – HAMMER).....	33
1.6.4 Description of parts or systems related to the occurrence (Mirage – GUSTO) .....	35
1.7 Meteorological information .....	36
1.8 Aids to navigation.....	37
1.9 Communications .....	37
1.10 Aerodrome information .....	38
1.11 Flight recorders .....	38
1.11.1 Cockpit Voice Recorder .....	38
1.12 Site of occurrence .....	38
1.13 Medical and pathological information .....	39
1.14 Fire .....	39
1.15 Survival aspects .....	39
1.16 Tests and research.....	39
1.17 Organisational and management information .....	39
1.17.1 The exercise in general.....	40
1.17.2 The Mission Commander’s (MC) workload.....	41
1.17.3 Principles for tactical control and flight information during the ACE exercise.....	41
1.17.4 Changes within the airspace during the exercise .....	42
1.17.5 Planning documentation for the blue forces. ....	42
1.17.6 Principles for separation .....	44
1.17.7 Operational Risk management Method (ORM) .....	46
1.18 Additional information.....	48

1.18.1	Actions taken.....	48
1.19	Special methods of investigation.....	50
2.	ANALYSIS .....	51
2.1	Introduction .....	51
2.2	The exercise ACE 17.....	51
2.3	Preconditions .....	52
2.3.1	Planning and preparations in general .....	52
2.3.2	ACO and ATO .....	52
2.3.3	The detailed planning for the blue forces.....	53
2.4	The near collision incident .....	53
2.4.1	General preconditions .....	54
2.4.2	The sequence of events according to recorded data.....	54
2.4.3	The event from the perspective of HAMMER.....	55
2.4.4	The event from the perspective of GUSTO .....	57
2.4.5	The event from the perspective of the tactical control .....	58
2.5	Organisation and management .....	59
2.5.1	The exercise in general.....	59
2.5.2	MC's workload.....	60
2.5.3	Principles for tactical control and flight information .....	60
2.5.4	Planning of airspace changes during the exercise .....	60
2.5.5	Principles for separation.....	61
2.5.6	Operational risk management method (ORM).....	62
2.6	Actions taken after the event .....	62
2.7	Overall assessment of the event.....	62
3.	CONCLUSIONS .....	64
3.1	Findings .....	64
3.2	Causes and Contributing Factors.....	65
3.2.1	Causes .....	65
3.2.2	Contributing Factors.....	65
4.	SAFETY RECOMMENDATIONS .....	67

## General observations and delimitations

The Swedish Accident Investigation Authority (Statens haverikommission – SHK) is a state authority with the task of investigating accidents and incidents with the aim of improving safety. SHK accident investigations are intended to clarify, as far as possible, the sequence of events and their causes, as well as damages and other consequences. The results of an investigation shall provide the basis for decisions aiming at preventing a similar event from occurring in the future, or limiting the effects of such an event. The investigation shall also provide a basis for assessment of the performance of rescue services and, when appropriate, for improvements to these rescue services.

SHK accident investigations thus aim at answering three questions: *What happened? Why did it happen? How can a similar event be avoided in the future?*

SHK does not have any supervisory role and its investigations do not deal with issues of guilt, blame or liability for damages. Therefore, accidents and incidents are neither investigated nor described in the report from any such perspective. These issues are, when appropriate, dealt with by judicial authorities or e.g. by insurance companies.

The task of SHK also does not include investigating how persons affected by an accident or incident have been cared for by hospital services, once an emergency operation has been concluded. Measures in support of such individuals by the social services, for example in the form of post crisis management, also are not the subject of the investigation.

Investigations of aviation incidents are governed mainly by Regulation (EU) No 996/2010 on the investigation and prevention of accidents and incidents in civil aviation and by the Accident Investigation Act (1990:712). The investigation is carried out in accordance with Annex 13 of the Chicago Convention.

### *Delimitations*

The planning and implementation of flight operations during the international exercise Arctic Challenge Exercise 2017 (ACE 17) used joint operation orders (EXOPORD – Exercise Operation Order) and special instructions (SPINS – Special Instructions) for all participants. SHK has therefore chosen in this investigation not to more closely discuss general national regulations for the armed forces concerned. SHK has, however, chosen to discuss the specific risk management methods that were used by the host countries for ACE 17.

During the exercise, the participants were divided into “blue” and “red” forces. Since the incident only involved two groups from the blue force, SHK has chosen not to more closely discuss activities or planning of the red forces.

The US Navy’s Tactical Air Operations Centre (TAOC) that participated in the exercise has not been more closely discussed since SHK believes that the unit’s operations did not have any decisive impact on the sequence of events. The reason for this is that the unit did not have any tactical control responsibility for the aircraft involved during the incident.

## The investigation

SHK was informed on 29 May 2017 that a serious incident between French and Swedish fighter aircraft had occurred in the exercise area ACE Center, north-west of Arvidsjaur, Norrbotten County, on 25 May 2017 at 15:00 hrs.

The incident has been investigated by SHK represented by Mr Jonas Bäckstrand, Chairperson, Mr Nicolas Seger, Investigator in Charge, Mr Gideon Singer, Operations Investigator from 16 August 2017, and Mr Stefan Carneros, Military Investigator from 30 October 2017.

Mr Ismo Aaltonen has participated as Finland's accredited representative on behalf of the Safety Investigation Authority of Finland.

Mr Roger Sjöberg has participated as an advisor for the Swedish Armed Forces.

During the initial stage of the investigation, SHK contacted the French military safety investigation authority, BEAD<sup>1</sup> Air. BEAD Air made reference to the French Armed Forces, which appointed the head of squadron at the French squadron in question as contact person for the investigation. In connection with the meeting with the interested parties (see below), SHK was informed that the military attaché at the French Embassy in Stockholm, Mr Fabrice Cohéleach, would henceforth be France's contact person.

### *Investigation material*

Interviews have been conducted with the pilots concerned, their superiors, the Swedish Air Surveillance and Control (STRIL), the exercise management and their safety organisation.

SHK has acquainted itself with the sequence of events through recordings of self-reported position data presented on D-ACMI<sup>2</sup>, audio files from the tactical control and Gripen's recording systems and also exercise documentation from the management for ACE 17. The investigation team has conducted an orientation session on a Mirage 2000 simulator and a review of the sequence of events in Gripen's mission support system for planning and debriefing (MSS<sup>3</sup>).

A meeting with the interested parties was held on 25 October 2017. At the meeting SHK presented the facts discovered during the investigation, available at the time.

---

<sup>1</sup> BEAD Air (Bureau Enquêtes Accidents Défense – air).

<sup>2</sup> D-ACMI (Debriefing – Air Combat Maneuvering Instrumentation) – A tool for following up and analysing military air combat operations and that utilises downloaded data from aircraft concerned.

<sup>3</sup> MSS (Mission Support System) – Gripen's mission support system for planning and debriefing.

*Abbreviations, terms and definitions*

AAR – Air-to-Air Refueling Area.

A/A – Air to Air.

ACO – Air/Airspace Control Order – An order implementing the airspace control plan for the exercise.

A/G – Air to Ground.

ASC 890 – Swedish Airborne Surveillance and Control unit.

ATO – Air Tasking Order – A method used to task and disseminate to components, subordinate units, and command and control agencies projected sorties, capabilities and/or forces to targets and specific missions. *Källa: DOD Dictionary of Military and Associated Terms as of June 2017.*

AWG – Airspace Working Group – The working group that prepared the airspace plan for ACE 17.

BENO MSN – Be No Mission – A line indicating the limit between two separate mission areas which shall not be crossed.

C2 – Command and Control – The authority, responsibilities and activities of military commanders in the direction and co-ordination of military forces and in the implementation of orders related to the execution of operations. *Source: AJP-3.3.5, ALLIED JOINT DOCTRINE FOR AIRSPACE CONTROL, Edition B Version 1, MAY 2013.*

CAP – Combat Air Patrol – An aircraft patrol provided over an objective area, the force protected, the critical area of a combat zone, or in an air defense area, for the purpose of intercepting and destroying hostile aircraft before they reach their targets.

COMAO – Composite Air Operations.

CRC – Control and Reporting Centre – A subordinate air control element of the tactical air control centre from which radar control and warning operations are conducted within its area of responsibility. *Source: AAP-06 2016.*

D-ACMI – Debriefing-Air Combat Maneuvering Instrumentation – A software used to monitor and analyze military air combat activity with the use of downloaded data from aircraft. The system compiles data and presents the desired event in a time-synchronized manner.

DCA – Defensive Counter Air.

ELEVATOR – In VMC (Visual Meteorological Conditions) aircrew may use the term “elevator (w/direction)”. This is a request from fighter to ACI/GCI to get bearing, range, altitude and track direction to the closest adversary group in requested direction. Based on this information, the aircraft may elect to climb/descend as required to desired altitude. SA on BLUE aircraft is assumed, and is not included in this request unless specifically requested. *Source: ACE 17, SPECIAL INSTRUCTIONS (SPINS) Change 3.*

FER – Final Exercise Report.

FLOT – Forward Line of Own Troops – A line which indicates the most forward positions of friendly forces in any kind of military operation at a specific time. *Source: AAP-6 2016.*

HMD – Helmet Mounted Display.

L16 – Link 16 – A military data link system, NATO Link 16, providing information about position and status of other units connected to the system.

Loose Advisory Control – A tactical control method where the pilot in command is responsible for, amongst other things:

- Keeping separation to the lateral and vertical boundaries of the exercise area.
- Deconfliction between other military aircrafts participating in the exercise or transiting through the exercise area.
- Navigation in accordance with current ACO for deconfliction.

*Source: ACE 17, SPECIAL INSTRUCTIONS (SPINS) Change 3.*

NAOC – Norwegian Air Operation Center – The center in Reitan responsible for planning and the issuing of ACO and ATO for the exercise.

OCA – Offensive Counter Air.

PM Wave – Post Meridiam Wave – Exercise wave during the afternoon.

QNH – Barometric pressure reduced to mean sea level.

RBFA – Rear Boundary of Forward Area – An airspace boundary between e.g. the refuelling areas and the remainder of the exercise area.

ROZ – Restricted Operations Zone – An area with restrictions for specific activities or operators, e.g. refuelling areas.

SA – Situation Awareness – A pilot’s continuous perception of self and aircraft in relation to the dynamic environment of flight, threats and mission, and the ability to forecast, then execute tasks based on that perception. *Source: McMillan, G. R. (1994). Report of the Armstrong Laboratory Situation Awareness Integration (SAINT) Team (Briefing Transcript). In Situation Awareness: Papers and Annotated Bibliography (U). Armstrong Laboratory, Wright-Patterson AFB: OH.*



SPINS – Special Instructions.

TAOC – Tactical Air Operation Centre – in this context, a United States unit, with the callsign EARTHQUAKE, participating in the exercise.

TC – Transit Corridor – Airspace corridors, usually in the outer portion of the exercise area, used for a safe transition.

WAM – Wide Area Multilateration – A ground based system using signals from aircraft to determine their position through triangulation, meaning measuring the time difference in response to a number of reception stations on the ground.

## Final report RM 2018:03e

---

Time of occurrence	25/05/2017, 15:00 hrs in daylight Note: All times are given in Swedish daylight saving time (UTC <sup>4</sup> + 2 hours)
Place	North-west of Arvidsjaur, Norrbotten County, (position 6542N 01851E, 6 650 metres above mean sea level)
Weather	According to SMHI's analysis at Flight Level 230: wind 300°/35 knots, visibility > 50 km, temperature minus 35°C, no significant clouds between Flight Levels 160 and 270, QNH <sup>5</sup> 1 007 hPa
<b>Aircraft: Group A (four aircraft)</b>	
Registration, type	215/831/222/283, JAS 39 Gripen
Call sign (in formation order)	HAMMER (11, 13, 12, 14)
Model	C/D
Class, Airworthiness	Military fighter aircraft
Operator	Swedish Armed Forces
Type of flight	Military exercise flight
Persons on board:	1/2/1/1
Crew member	1/1/1/1
Passengers	0/1/0/0
Injuries to persons	None
Damage to aircraft	No damage
Other damage	No damage

All pilots had a valid military certificate and were competent on the type with valid OPC<sup>6</sup>.

The pilots had flown the type for at least eight years and accumulated at least 700 flying hours on Gripen.

All pilots had at least eight hours' continuous rest time every night during the 72 hours before the event.

---

<sup>4</sup> UTC (Coordinated Universal Time).

<sup>5</sup> QNH (Barometric pressure reduced to mean sea level).

<sup>6</sup> OPC (Operator Proficiency Check) – The operator's check of the pilot's competence.

**Aircraft: Group B (two aircraft)**

Registration, type	102 (F-UHKR), 113 (F-UHYO), Mirage 2000
Call sign (in formation order)	Gusto (55, 56)
Model	C RDI
Class, Airworthiness	Military fighter aircraft
Operator	French Air Force
Type of flight	Military exercise flight
Persons on board:	1/1
Crew member	1/1
Passengers	0/0
Injuries to persons	None
Damage to aircraft	No damage
Other damage	No damage

All pilots had a valid military certificate and were competent on the type with valid OPC.

The pilots had flown the type for at least two years and accumulated at least 300 flying hours on Mirage 2000.

Both pilots had at least eight hours' continuous rest time every night during the 72 hours before the event.

## SUMMARY

A serious near collision incident occurred on 25 May 2017 during the international military exercise Arctic Challenge Exercise 2017 (ACE 17), in the airspace north-west of Arvidsjaur in Norrbotten County, Sweden.

A group consisting of four Swedish Gripen aircraft was flying south in level flight during its return to base phase after an aerial combat mission. At the same time, a group consisting of two French Mirage aircraft were flying north during a descent after completion of aerial refuelling.

One of the Mirage aircraft passed very close to one of the Gripen aircraft. The aircraft had visual contact with each other just before passage. Neither of the pilots performed any evasive manoeuvres.

The maintenance of separation between the aircraft was based on an overall airspace separation that was planned by the exercise management and was published in the form of an Airspace Control Order (ACO) and an Air Tasking Order (ATO). The Mission Commander (MC) for the exercise and his team then performed the detailed planning that was published in the form of a coordination card. The two aircraft groups interpreted the information received in different ways. This was in part due to their digital maps not showing the same information. Furthermore, important information was lacking in both the Airspace Control Order and the Air Tasking Order.

The event occurred in the exercise area that applied a tactical control method called “Loose Advisory Control”, which means, among other things, that the pilots themselves had responsibility for maintaining their own separation in relation to the exercise area’s lateral and vertical boundaries and to other military aircraft that were participating in the exercise.

The Mirage group, whose radar sensors were inactive, called the tactical control to get information about other traffic, but never received any response. The Mirage group executed the descent since they considered themselves to have a good situation awareness (SA).

According to NATO’s manual regarding exercise rules for aerial combat, the pilots could ensure their separation with other aircraft based on situational awareness (SA), geography, timing, on-board systems, GCI/AEW, visual contact, other fighters, or any other appropriate aid.

The cause of the event was that the exercise management underestimated the risks of separation infringement during the administrative flight phases of the exercise, which led to the exercise being conducted with latent collision risks.

Contributing factors were that:

- ACO was changed daily and lacked procedures and routes for transition between aerial refuelling and combat missions, and between combat missions and egress for the return to base.

- The limited content in ACO and ATO resulted in an extensive workload for the MC team.
- The term SA was not clearly defined, which gave the participants scope for different interpretations of, e.g., the altitude change procedure, ELEVATOR.

### **Safety recommendations**

#### **The Swedish Armed Forces is recommended, in consultation with the Finnish and Norwegian armed forces, to:**

- Examine the need of clarifying the term SA (Situation Awareness) in the exercise rules contexts in which the term is used. *(RM 2018:03 R1)*
- Examine the need to address risks regarding administrative flight phases in connection with exercises and operations. *(RM 2018:03 R2)*
- Examine the need to conduct a simulation in order to validate the separation plan before the exercise. *(RM 2018:03 R3)*
- Evaluate the need and the possibilities to share recognized air picture with more participating units. *(RM 2018:03 R4)*

## 1. FACTUAL INFORMATION

### 1.1 History of the flight

#### 1.1.1 *Preconditions*

The event occurred in connection with an international military air exercise, called ACE 17 (Arctic Challenge Exercise 2017).

ACE is a recurrent multinational air exercise that takes place in the northern parts of Finland, Norway and Sweden and that was also conducted in 2013 and 2015. The exercise was conducted as part of the Nordic cooperation and a cross-border agreement called Cross Border Training that exists between the countries.

ACE 17 was conducted during the period 22 May to 2 June 2017. During ACE 17, just over 100 aircraft from several countries participated, as well as support flights and ground units. In addition to the Swedish and French aircraft, units also participated from the Belgian, British, Canadian, Dutch, Finnish, German, Norwegian, Spanish, Swiss and US air forces (see Figure 1).



Figure 1. ACE 17 logotype. Source: Armed Forces (Finland).

The aim of ACE is to exercise and train units and C2 (Command and Control<sup>7</sup>) in the orchestration and conduct of air operations and to practice tactics and command and control procedures.

<sup>7</sup> C2 (Command and Control) – The powers, responsibilities and activities of military officers to lead and coordinate military units and to implement orders related to the execution of missions.

The fighter aircraft proceeded from three different airports; Luleå in Sweden (ESPA), Rovaniemi in Finland (EFRO) and Bodø in Norway (ENBO). The tactical control in the respective countries controlled the aircraft to and from the exercise area.

Within the combat areas themselves there was only an information service, called “Loose Advisory Control”, which meant that the pilots were responsible for maintaining their own separation in relation to the exercise area’s lateral and vertical boundaries and to other military aircraft that were participating in the exercise. The pilots also had the possibility, where necessary, to request information about other traffic from the tactical control.

The planning for the exercise was commenced at the beginning of the year with a series of planning conferences in Oslo to lay the foundations for the exercise and to secure experience from previous exercises.

The geographical extent of the exercise area is shown in Figure 2.




Figure 2. The geographical exercise area for ACE CENTRE within Sweden marked with a broad grey line. Source: Armed Forces (Sweden).



The exercise area's demarcations regarding the airspace are shown in Figure 3.




Figure 3. ACE 17 airspace areas. Source: Armed Forces (Finland).

The event occurred during the fourth day of the exercise and during the afternoon session PM Wave<sup>8</sup>. The exercise was planned as an operation with several missions that, among other things, covered aerial combat, combating ground targets and aerial refuelling.

As part of the safety management, the Finnish and Swedish air forces performed risk analyses in order to identify and limit risks during the exercise. These are presented in more detail in section 1.17.

The airspace planning was conducted by the Norwegian Air Operations Center (NAOC), where an Airspace Working Group (AWG) issued both Airspace Control Orders (ACO) and Air Tasking Orders (ATO).

The detailed planning ahead of each session was performed by specially designated commanders (including in the role of MC – Mission Commander and Airboss) with associated staff as described in more detail in section 1.17.

The Deconfliction Plan between the aircraft was based on pre-planning of elements in time and space.

<sup>8</sup> PM Wave (Post Meridiem Wave) – Refers to exercise sessions during the afternoon.

The Deconfliction Plans consist in principle of ACO (Airspace Control Order), ATO (Air Tasking Order) and Coordination card.

The session in question was preceded by meetings and reviews (briefings) in various steps. The briefings had a particular focus, among other things, on separation, safety and on administrative and tactical procedures. Since the participants proceeded from three different bases, the briefings were conducted through video teleconference (VTC).

The exercise participants were divided into a blue and a red force. Each side was assigned its own areas, airspaces, flight altitudes and times as well as aerial refuelling areas and refuelling times.

The blue forces' planned missions are shown in Figures 4 and 5, which show sortie scope as well as participating aircraft and groups of aircraft, including assigned times and altitudes.

The Swedish group, which consisted of four JAS 39 Gripen (a four-ship), had the call sign HAMMER 11. The four-ship's members were called HAMMER 11, 12, 13 and 14. The four-ship's mission is shown in Figures 4 and 5, marked in green. Upon the meeting with the French Mirage aircraft (the passage), the group had a formation in the order HAMMER 11, 13, 12, 14.

The French group, which consisted of two Mirage 2000C (a two-ship), had the call sign GUSTO 55. The two-ship's members were called GUSTO 55 and 56. The two-ship's mission is shown in Figures 4 and 5, marked in blue.

The coordination card shows that HAMMER was assigned an aerial combat mission (A/A<sup>9</sup>) at an altitude block of 22 000–24 000 feet<sup>10</sup> while GUSTO was assigned a ground attack mission (A/G<sup>11</sup>) at a holding pattern altitude of 16 000 feet.

During the exercise, "Force QNH" was used, which meant that all participants used the same altitude reference regarding altimeter setting.

The time allocation table (see Figure 5) shows that HAMMER was to be finished with its mission and return to the base at around the same time as GUSTO was to commence its attack mission.

---

<sup>9</sup> A/A (Air to Air) – Refers to aerial combat between airborne units.

<sup>10</sup> Foot – Unit that corresponds to 0.3048 metres.

<sup>11</sup> A/G (Air to Ground) – Refers to the combating of ground targets from the air.

BLUE COORDINATION CARD				Package			MJÖLNIR					MC		BOW57	
				Date			2017-05-25		Ch	9	DMC	VERMIN15			
CALLSIGN	# / TYPE	MSN	AA WPN	AG WPN	MODE 3	STN	AA TAC	TAXI	T/O	IN ALT	push AL	2.push	HOLD PT	HOLD ALT	
STORK 51	4*M2000-5	A/A	402+	NIL	4151	10220	38Y	1123	1133	31	35-36		HC	35-36	
PANTHER 21	4*F18	A/A	602+	NIL	2421	10330	21Y	1150	1200	23	25-26		HE	25-26	
PANTER 25	2*F18	A/A	602+	NIL	2425	10334	23Y	1240	1250	24	35-36		HE	35-36	
DALTON 05	4*JAS-39	A/A	402+	NIL	2405	10264	15Y	1155	1205	21	31-34	25-26	HE / HE	31-34 / 25-26	
DALTON 35	2*JAS-39	A/A	402+	NIL	2435	10268	16Y	1205	1215	21	11-12		HE	11-12	
HAMMER 11	4*JAS-39	A/A	402+	NIL	2411	10270	17Y	1148	1158	22	22-24		HC	22-24	
JAKAL 01	4*F16	A/A	600+	NIL	1501	10200	02Y	1140	1150	24	31-34	25-26	HW / HW	31-34 / 25-26	
JAKAL 05	4*F16	A/A	600+	NIL	1505	10204	4Y	1135	1145	25	25-26		HW	25-26	
BOW 57	2*RAF	A/G	202+	12*SB38	4157	10224	38Y	1120	1130	30	15		HE	15	
GUSTO 55	2*M2000C	A/G	002+	2*GBU-24	4155	NIL	38Y	1155	1205	33	16		HC	16	
STEEL 21	4*F18	A/G	202+	8*GBU-31	4121	10310	26Y	1145	1155	32	13-14		HE	13-14	
GATOR 21	4*JAS-39	A/G	202+	32*SDB	1521	10300	10Y	1125	1135	26	-16, 20-		HW	14-16, 20-21	
VERMIN 15	4*GR4	A/G	002+	STORM SHADOW	1515	10234	08Y	1240	1250	20	LO+10-13		HC	LO+10-13	
GOLD 25	2*JAS-39	AG	202+	16*SDB	1525	10304	12Y	1125	1135	21	-16, 20-		HW	14-16, 20-21	
FANG 11	4*F16	A/A	402+	NIL	1511	10240	6Y	1120	1130	23	35-36		HW	35-36	
TECHNO 74	1*DA-20				1574				1140						
YETI 72	1*C130				1572		41Y	1120	1130					LO+10	
WILLOW 73	1*C295				4173		104Y	1120	1125					LO+10	
SKIBOX 74	1*ASC-890				2474	35				20					
TEXACO71	KDC-10	AAR				EHEH	111Y/48Y	0905	0915	25KFT	60K	ROZ 7H	BOOM	80K ON REG	
SHELL73	A330-V	AAR				EGVN	113Y/50Y	0840	0850	26KFT	60K	ROZ 6H	DROGUE		
QUID77	KC135M	AAR													
COBOT72	A-310	AAR			4172	EFRO	112Y/47Y			26KFT	80K	ROZ 9H	DROGUE	SINGLE HOSE	

Figure 4. Time coordination card for the blue forces. Source: Armed Forces (Sweden).

IN ORDER OF PUSH / ROLLCALL																
CALLSIGN	INFLIGHT	PUSH 1			PUSH2			ALT TO	FLOW A/A			TGT 1	TOT	TOT ON STA	EGRESS	
		FREQ'S	TARC	TIME	TARC ALT	TARC	TIME		TARC ALT	1	2				3	ROZ 1
STORK 51		E1	1235	31-34				1210	AAR	E1				1240-1330	31	EFRO
PANTHER 21		E2	1245	21-24					AAR	E2				1255-1335	23	ESPA
PANTER 25		E1	1315	31-34						E1				1315-1400	24	ESPA
DALTON 05		E1	1228	31-34	E2	1335	21-24		E1	AAR	E2			1330-1400	21	ESPA
DALTON 35			1300	11-12					AAR	SLOMC				1300-1400	21	ESPA
HAMMER 11		W2	1228	22-24					SWEET	W2				1225-1300	22	ESPA
JAKAL 01		W1	1229-45	31-34	W2	1325	22-24		W1	AAR	W2	1300Z->	B21-24	1330-1400	24	ENBO
JAKAL 05		W2	1300	22-24					AAR	W2		1300Z->	B21-24	1300-1330	25	ENBO
BOW 57		E	1233	15						BACK E		6	1240-1250		32	EFRO
GUSTO 55		E	1309	16								39	1315-1325		33	EFRO
STEEL 21		E	1233	13-14						BACK E		6	1240-1250		30	EFRO
GATOR 21		BC W	1234	14-16, 20-21						BACK V		2	1240-1250		26	ENBO
VERMIN 15		E	1330	LO+10-13								51	1340-1350		20	ENBO
GOLD 25		BC W	1234	14-16, 20-21				1138				2	1240-1250		21	ENBO
FANG 11		W1	1235	31-34				1235	AAR	W1				1240-1330	23	ENBO
TECHNO 74		E	1229	20										1230-1400	20	ENBO
YETI 72		E	1305	LO+10								49	1330-40			ENBO
WILLOW 73		E	1305	LO+10								49	1330-40			EFRO
SKIBOX 74		ROZ1	20													

Figure 5. Time allocation table. The times in the table are given in UTC, which means that two hours are to be added to obtain local time at the time of the exercise. Source: Armed Forces (Sweden).

### 1.1.2 Sequence of events

According to the D-ACMI<sup>12</sup> system, GUSTO 55 and HAMMER 12 passed each other at 14.59.53 hrs, and the closest measured distance was about 150 metres horizontally and 30 metres vertically. The position image is shown in Figure 6.

The D-ACMI position is based on downloaded navigation data from the aircraft. The measured horizontal distance has an uncertainty on account of differences in the flight groups' air navigation equipment that can amount to 50–60 metres.

<sup>12</sup> D-ACMI (Debriefing – Air Combat Maneuvering Instrumentation) – A tool for following up and analysing air combat operations.



Figure 6. The position image according to D-ACMI centred around HAMMER 12 during the incident at 15:00 hrs. (The Mirage two-ship GUSTO 55/56 is flying north and Gripen HAMMER 12 south). Source: Armed Forces (Sweden).

A schematic vertical position image of the event before, during and after the incident is presented in Figures 7, 8 and 9. The images are not to scale.




Figure 7. Vertical schematic position image before the incident at approximately 14:58 hrs.




Figure 8. Vertical schematic position image during the incident at approximately 15:00 hrs.



Figure 9. Vertical schematic position image after the incident at approximately 15:02 hrs.

The Swedish Armed Forces’ analysis of Air Navigation Services of Sweden’s (LFV) readings of the aircraft’s position according to WAM<sup>13</sup> measurements shows that the distance was about 0.08 Nm (150 m) at the same altitude.

SHK has also examined transponder data where the distance between GUSTO 55 and HAMMER 12 was measured to be 480 metres during the passage (see Figure 10).

<sup>13</sup> WAM (Wide Area Multilateration) – A ground-based system that uses the signals transmitted from an aircraft in order to determine its position by means of triangulation, which entails measuring the time difference of responses to a number of receiving stations on the ground.




Figure 10. Measured distance between GUSTO 55 and HAMMER 12. Source: Armed Forces (Sweden).

A few minutes before the incident, GUSTO was located in the southern part of the exercise area and had just concluded aerial refuelling in the aerial refuelling zone called AAR ROZ-8 (Air to Air Refueling Restricted Operating Zone 8).

GUSTO left the refuelling area at an altitude of 27 000 feet on a north-northeasterly heading in a two-ship formation en route to a holding pattern called HOLD CENTRE in order to begin its attack mission. According to the planning, GUSTO was to be at 16 000 feet before the mission was commenced.

At the same time, HAMMER, which was in a dispersed trail formation, concluded its aerial combat mission in the central part of the exercise area and was en route to reassemble into a tactical formation in order to return to Luleå. Initially, the group members utilised the altitude block between 22 000 and 24 000 feet to then fly south in an extended trail formation at 22 000 feet.

HAMMER 11 and 13 were forwardmost in a two-ship formation and were flying south to then commence a left turn towards the eastern transit corridor before the return to base. A few nautical miles behind followed HAMMER 12 and a few more nautical miles further back followed HAMMER 14. The dispersed formation constituted a tactical group that was led by HAMMER 11.

At around the same time, GUSTO wanted to commence its descent from 27 000 feet to 16 000 feet en route towards the holding pattern called HOLD CENTRE. In connection with the incident, the radar sensors on GUSTO 55 or 56 did not deliver any target data to the pilots because the radar sensor on GUSTO 55 was temporarily inoperative, while the radar sensor on GUSTO 56 was intentionally set to standby mode.

GUSTO then attempted to get information concerning nearby aircraft ahead of its descent through a radio call (ELEVATOR call) to the tactical control. The call was made both on the primary and secondary frequencies (with call sign EARTHQUAKE and EAGLE, respectively). SHK has listened to the sound recordings but it has not been possible to perceive any response to GUSTO's call.

The close passage occurred between GUSTO 55 and HAMMER 12 (which was third in the formation) at approximately 22 000 feet.

After the passage, HAMMER and GUSTO continued as planned.

The incident was reported verbally after the session and then in writing according to applicable procedures.

The event was also raised at the major debriefing (MASS DEBRIEF) the same day.

The incident occurred at position 6542N 01851E, 22 000 feet (6 650 metres) above mean sea level.

### **1.1.3 *The sequence of events from the perspective of HAMMER (the Gripen group)***

The sequence of events from HAMMER's perspective has been documented through the group's radio communications, Gripen recordings and through interviews with all pilots.

HAMMER's electronic map image that was presented on the tactical indicator is shown in Figure 11. The map is oriented in the aircraft's longitudinal axis and displays a view in a roughly southerly direction with its own position marked as a black triangle in the centre.

The planned route is displayed with blue lines. Airspace boundaries are indicated with red and brown lines. Aircraft belonging to its own forces are indicated in green, where filled green symbols, e.g. D/22, represent HAMMER's group members, and green symbols without filling represent other aircraft.




Figure 11. Gripen's digital map at about the time of the incident. Source: Armed Forces (Sweden).

The aircraft's map image was created via a planning service and a support system (Mission Support System) by means of Airspace Control Orders and Air Tasking Orders (ACO/ATO), and with adaptation to the aircraft's and the mission's limitations.

The interviews show that the HAMMER group was finished with the aerial combat mission in the western area and was in the process of reassembling ahead of the return to Luleå. As a part of the aerial combat tactics, the group was dispersed during the egress of the mission and return to base and monitored the formation by means of the aircraft's own radar and information via data link.



All group members maintained the assigned altitude of 22 000 feet in accordance with the mission planning and considered the flight phase an administrative flight phase<sup>14</sup> for reassembly and reversion to a routine return to base.

The group leader perceived the red line east of the group as being a hard boundary that was not to be passed (BENO MSN<sup>15</sup>), so as not to conflict with other aircraft from the blue force. The digital map shows the pre-programmed route for return to base in blue. The route went between two lines that formed an east-west corridor to then continue in a northbound direction all the way to a report point marked W9 (see Figure 11).

The group members have related that the mission transitioned to a calmer reassembly phase ahead of the return to base. They perceived that they were separated in altitude from other traffic and therefore refrained from locking the radar on this.

The Gripen aircraft were equipped with a data link system, NATO Link 16, which provides information on flight position and status of other units connected to the data link.

The interviews show that GUSTO did not appear in the data link system since the Mirage aircraft were neither equipped with Link 16 nor defined as link targets by the tactical control.

The incident report shows that the group head for HAMMER was following the GUSTO two-ship on the radar and observed that they had left their cruising altitude of 27 000 feet and were beginning to descend towards the HAMMER group in the direction of the western part of the combat area (West Lane).

By means of radar target data presented on his helmet display (HMD<sup>16</sup>), the group leader discovered the Mirage two-ship visually at a vertical distance of less than 2 000 feet and informed his group of this via radio.

The Mirage two-ship formation passed above the first two HAMMER members and was discovered visually shortly thereafter as a very close passage by the third HAMMER member (HAMMER 12). HAMMER 12 did not perform any evasive manoeuvre.

The fourth HAMMER member that was a few more nautical miles further back, as the last aircraft in the trail, saw the passing Mirage aircraft below with good separation.

---

<sup>14</sup> Administrative flight phase – Refers to a flight phase to and from combat area.

<sup>15</sup> BENO MSN (Be No Mission) – Refers to a line that may not be encroached during the mission.

<sup>16</sup> HMD (Helmet Mounted Display).

The pilots have stated that the radio traffic on the administrative frequency was strained and that many were trying to communicate simultaneously with the tactical control without always being able to perceive any response.

In interviews with pilots and fighter controllers, it has also been pointed out that the tactical control TAOC, with the call sign EARTHQUAKE, had limited radio coverage and delivered misleading aircraft positions on Link 16.

#### **1.1.4 *The sequence of events from the perspective of GUSTO (the Mirage two-ship)***

The sequence of events from GUSTO's perspective has been documented through the group's radio communications and interviews with both pilots.

The digital map that was available to the Mirage pilots during the session is shown in Figure 12. The map is north-oriented without specifically showing the aircraft's own position. The incident took place roughly between the points on the map designated ACE RBFA<sup>17</sup> and HOLD CENTRE.

GUSTO's planned route is displayed as blue lines with numbered navigation points. The airspace boundaries and demarcation lines are shown in red, while orange-coloured lines mark corridors. In addition to this, markings are presented for holding pattern, ground targets and various reference points in the form of letters and numbers.

---

<sup>17</sup> RBFA (Rear Boundary of the Forward Area).




Figure 12. The digital map that was available to the Mirage pilots during the mission on their electronic knee boards. Source: Armed Forces (France).

The interviews show that the GUSTO two-ship was finished with the aerial refuelling mission in the central area (ROZ8) and was to be reassembled ahead of the attack mission.

According to the time allocation table (see Figure 5), the attack mission was to proceed from the holding pattern HOLD CENTRE at an altitude of 16 000 feet at 15:09 hrs.

The two-ship wingman had his radar in standby mode since the two-ship was in close formation and so as not to disturb the two-ship leader with radar warnings. Besides this, the two-ship leader's radar was temporarily inoperative, which entailed that the two-ship had no radar capability whatsoever during the initial approach towards the holding pattern.

The Mirage aircraft did not have access to their radar sensors during the descent phase, nor were they equipped with the data link system, L16. This meant that the pilots needed to rely on radio contact with the tactical control and on its own visual scanning of the airspace.

The interviews show that the pilots assessed that they had a good situation awareness (SA<sup>18</sup>) and that they did not expect that there would be other aircraft on the route to the holding pattern.

<sup>18</sup> SA (Situation Awareness) – Refers, among other things, to the pilot's awareness of his position in relation to the surroundings.

The incident report shows that GUSTO, as planned, left the flight altitude of 27 000 feet and descended on heading 040° to the assigned altitude of 16 000 feet in the corridor (between two orange-coloured lines – see Figure 12) between Point D (hidden under the text ACE RBFA) and the holding pattern HOLD CENTRE. According to the same incident report, GUSTO 55 and 56 discovered four oncoming aircraft at close quarters.

The two-ship leader has related that he called the tactical control with a request for traffic information ahead of the altitude change (ELEVATOR CALL) but never perceived any response, either on the primary or on the secondary frequency.

The two-ship leader's decision, as planned, to leave 27 000 feet and descend quickly to 16 000 feet was based on the fact that it was necessary to arrive in time and to be at the right altitude ahead of the attack mission. Besides this, the two-ship leader perceived that he had a good SA with reference to the weather and his mental picture of the surrounding traffic. He has related that he trusted the exercise's Deconfliction Plan and that he was aware that it was the pilots themselves who were responsible for the separation in the area.

The GUSTO members, whose radar units were not active, did not have visual contact with HAMMER 12 until some seconds before the passage.

The interviews show that GUSTO's two-ship leader spotted two Gripen aircraft in formation under him and on his left side. A couple of seconds later, a third Gripen aircraft was spotted. The meeting with the third Gripen aircraft was perceived as very close and the distance was estimated at between 200 and 300 metres at the same altitude.

GUSTO did not perform any evasive manoeuvres. The two-ship leader has explained that an evasive manoeuvre would not have changed anything. Besides this, he considered that an evasive manoeuvre to the right was not appropriate with reference to his two-ship wingman who was flying on the right side of him.

After the passage, the GUSTO members were worried about where the fourth Gripen aircraft was located, but they never obtained visual contact with it.

After the incident, GUSTO continued with the planned mission and subsequently returned to Rovaniemi.

### 1.1.5 *The sequence of events from the perspective of the tactical control*

During the exercise, the tactical control responsibility in the Swedish part of the exercise area was delegated from the Norwegian control centre (NAOC) to the Swedish tactical control unit (CRC – Control and Reporting Centre) with the call sign EAGLE (see Figure 13).




Figure 13. Tactical control responsibility during ACE 17. Source: Armed Forces (Finland).

As a part of the exercise, other units also received partial responsibility during the session in question. The US unit, TAOC, with the call sign EARTHQUAKE, was, amongst other things, responsible for providing flight information upon request within that part of the combat area in which the incident took place, while EAGLE only had backup responsibility.

In addition to these ground units, a radar surveillance and control aircraft was in the air. The aircraft constituted an airborne radar and tactical control platform with the designation ASC 890. The unit was in the air during the afternoon session, but its main task was only to reconnoitre with its own radar in the area's northern sector and assist EARTHQUAKE with recognized air picture on Link 16.

According to interviews with the Swedish fighter controller, he perceived that GUSTO requested flight information ahead of an altitude change (ELEVATOR) from EARTHQUAKE without receiving any response.

When GUSTO commenced its descent, the fighter controller discovered that the groups were on collision course but assumed that these had visual contact with each other and therefore took no action.

During the passage, HAMMER and GUSTO were on different tactical control frequencies in accordance with the applicable planning.

The fighter controller has also related that the frequency that was to be used for the transition from the aerial refuelling area to the holding pattern HOLD CENTRE was a tactical frequency that might have been jammed.

According to EAGLE's report, GUSTO concluded its aerial refuelling at 14:55 hrs and called EARTHQUAKE on the aerial refuelling frequency with a request to be permitted to leave the area.

It is furthermore apparent from the report that aircraft could leave the aerial refuelling frequency and transfer to the check-in frequency instead of the tactical frequency. This constituted a complicating factor for the fighter controller, who was thereby not sure which frequency GUSTO was on.

#### **1.1.6 *The sequence of events from the perspective of the Mission Commander***

It is apparent from the Airspace Control Orders (ACO) and Air Tasking Orders (ATO) that were handed out to the participants at 13:00 hrs the day before the afternoon exercise session (PM Wave) that the basic planning was only an overview and presupposed that much of the detailed planning work would be done by the Mission Commander (MC) for the exercise.

Since the participants proceeded from the three bases Luleå, Rovaniemi and Bodø, some of the planning was conducted via video teleconference.

The Mission Commander's task was to plan the missions, allocate flying units, weapons and targets and to perform the detailed planning of tactics, airspace and coordinate other resources, such as aerial refuelling.

Within the limited time ahead of the briefing, the Mission Commander's team needed to plan, test, analyse and have the planning approved by the AIRBOSS for the exercise.

The interviews with several of the key persons show that their perception of how the missions were to be carried out in practice differed, particularly with regard to the administrative flight phases into and out of the combat area.

It is also apparent from the interviews that some details were only conveyed verbally during the review or only to individual pilots after the review.

It is also apparent that the Mission Commander believed that the separation line (BENO MSN) was supposed to end further north than the position indicated by the briefing card's coordinates and that the egress procedure was not presented during the review.

According to interview information, the GUSTO pilots had a separate meeting with the Mission Commander after the joint review and asked how the flight from the refuelling area to the attack mission was intended to be carried out. The Mission Commander then explained the procedure, which was then also applied by GUSTO.

## 1.2 Injuries to persons

None.

## 1.3 Damage to aircraft

No damage.

## 1.4 Other damage

No damage, no environmental impact.

## 1.5 Personnel information

### 1.5.1 Qualifications and duty time of the pilots

#### *Group A (Gripen, call sign HAMMER)*

JAS Gripen Pilots	Age	Total flying hours	On the type	Latest 90 days	Type rating year	Latest OPC <sup>19</sup>
Hammer 11	37	1680	1270	36	2008	Aug. 2016
Hammer 12	41	1940	1005	38	2006	Aug. 2016
Hammer 13	44	2000	755	46.5	2003	Dec. 2016
Hammer 14	47	2200	1100	20	2001	Dec. 2016

All pilots had a valid military certificate with flight operational and medical eligibility.

All pilots had at least eight hours' continuous rest time every night during the 72 hours before the event.

#### *Group B (Mirage, call sign GUSTO)*

Mirage Pilots	Age	Total flying hours	On the type	Latest 90 days	Type rating year	Latest OPC
Gusto 55	31	990	600	50	2013	Jul. 2016
Gusto 56	29	850	360	65	2015	Feb. 2017

All pilots had a valid military certificate with flight operational and medical eligibility.

All pilots had at least eight hours' continuous rest time every night during the 72 hours before the event.

### 1.5.2 Passengers

HAMMER 12 had one passenger who did not have any operational role during the mission.

<sup>19</sup> OPC (Operator Proficiency Check) – The operator's check of the pilot's competence.

### **1.5.3 Other personnel**

Relevant units during the incident were the Swedish tactical control unit (EAGLE), the US Navy's tactical control unit (EARTHQUAKE) and the airborne surveillance control aircraft ASC 890 (SKIBOX).

The Swedish tactical control personnel were to some extent involved in the event and were actors in the ACE 17 exercise as regards planning and implementation.

However, the tactical control had no separation responsibility in the area in question during the afternoon session but could, where necessary, provide a picture of flight position to calling aircraft.

Members from EAGLE and SKIBOX have been interviewed. Since the tactical control personnel did not conduct tactical control in the area in question, their personnel information is not reported.

## **1.6 Aircraft information**

### **1.6.1 Aircraft A – Gripen general**

JAS 39 Gripen is a single-engine multirole fighter aircraft manufactured by Saab AB, (see Figure 14). The A and C versions are single-seaters, while the B and D versions are two-seaters. The aircraft is 14.1 metres long and has a span of 8.4 metres. Maximum permitted take-off weight is 14 000 kg.



Figure 14. Gripen C. Photo: Saab AB.

The aircraft's sensors and navigation system considered to be relevant to the occurrence are described in section 1.6.3.



### ***1.6.2 Aircraft B – Mirage 2000 general***

Mirage 2000 is a single-engine multirole fighter aircraft manufactured by Dassault Aviation, (see Figure 15). The model C RDI is a single-seat fighter version with multifunction Doppler radar. The aircraft is 14.6 metres long and has a span of 9.1 metres. Maximum permitted take-off weight is 16 500 kg.



Figure 15. Mirage 2000C RDI. Photo: Armed Forces (France).

The aircraft's sensors and navigation system considered to be relevant to the occurrence are described in section 1.6.4.

### ***1.6.3 Description of parts or systems related to the occurrence (Gripen – HAMMER)***

The aircraft is equipped with an inertial navigation system with GPS (INS/GPS). Navigation points are presented to the pilot in different ways in the cockpit, including in the tactical indicator (TI) and on the display indicator (Head Up Display – HUD), (see Figure 16).



Figure 16. Gripen C cockpit. Navigation display in the centre with HUD above and in front of the front windscreen. Photo: Saab AB.

The aircraft is equipped with a main sensor in the form of a multi-function pulse-Doppler radar that, among other things, can detect and follow several aerial targets simultaneously. The aircraft is also equipped with a helmet display (Helmet Mounted Display – HMD) called COBRA. On the helmet display, flight and radar target data, among other things, can be presented to the pilot in the form of various visual symbols, see Figure 17.



Figure 17. Gripen Cobra helmet display (HMD). Photo: Saab AB.

The navigation system on Gripen is fully integrated with the presentation and manoeuvring system. The planned route as well as underlying map documentation is loaded via the planning and debriefing system (Mission Support System – MSS).

#### 1.6.4 Description of parts or systems related to the occurrence (Mirage – GUSTO)

The aircraft is, among other things, equipped with an inertial navigation system (INS), with 10 primary and 10 secondary navigation points that are presented to the pilot in different ways in the cockpit, including in the display indicator (Head Up Display – HUD), see Figure 18.

The aircraft is equipped with a main sensor in the form of a multi-function pulse-Doppler radar that, among other things, can detect and follow several aerial targets simultaneously.

In connection with the event, the radar sensor on GUSTO 55 was temporarily inoperative, while the radar sensor on GUSTO 56 was intentionally set to standby mode.

The temporary functional interruption to GUSTO 55's radar was restored later during the flight in question and did not occasion any maintenance measures.



Figure 18. Mirage 2000C RDI cockpit. Photo: Armed Forces (France).

The pilot also has access to a GPS-equipped Samsung Note 8 tablet, (see Figure 19).

The tablet was equipped with a multi-layered map application called Alliance that contained maps, relevant points and polygons from the ACE 17 documentation. The application was developed by the French Air Force for its needs, and the mission planning was done on a computer called Mission Planning Computer and was downloaded to the pilots' tablets ahead of every mission.




Figure 19. The navigation application in a Note 8 tablet used by the French Air Force in Mirage 2000C. Photo: Armed Forces (France).

## 1.7 Meteorological information

The forecast that was applicable at the time of the incident is shown in Figure 20.

The forecast shows, among other things, that there would not be any clouds above Flight Level 180 in the area in which the incident took place.




Figure 20. Weather forecast that was part of the review ahead of the afternoon session in question. Source: Armed Forces (Finland).

Weather according to SMHI's analysis at about Flight Level 230 at the time of the event:

- Wind 300°/35 knots
- Visibility > 50 km
- Temperature minus 35°C
- No significant clouds between Flight Levels 160 and 270
- QNH<sup>20</sup> 1007 hPa

## 1.8 Aids to navigation

Aids to navigation that were relevant to the event were carried on board and are discussed in more detail in sections 1.6.3 and 1.6.4.

## 1.9 Communications

In connection with the incident, both the JAS and Mirage groups (HAMMER and GUSTO) were in a transition phase out from the combat area and into the combat area, respectively, which meant that they were located in an area in which the pilots themselves had responsibility for the separation.

There were two tactical control units that could be used by the groups on different frequencies in order to receive traffic information where necessary. These were the US Navy's tactical control unit (TAOC with call sign EARTHQUAKE) and the Swedish tactical control unit (CRC with call sign EAGLE).

Shortly before the incident, HAMMER switched from the tactical control frequency to the recovery frequency.

<sup>20</sup> QNH (Barometric pressure reduced to mean sea level).

GUSTO called EARTHQUAKE several times on the primary and the secondary frequency before the altitude change in order to get traffic information, but never obtained any contact. Only after the passage of HAMMER 12 did GUSTO call the frequency that applied for the attack mission.

In connection with the incident, HAMMER and GUSTO were on different frequencies. The only common frequency for the groups was the emergency frequency called GUARD. No communication has been registered on this frequency during the sequence of events.

It has emerged through the interviews that there were disruptions in the radio traffic, that it was at times strained and that a frequency change was sometimes necessary in order to obtain contact. Deliberate interference of radio frequencies is common during this type of exercise.

The Swedish tactical control unit, CRC EAGLE, constituted a backup to that of the US unit, EARTHQUAKE. Limited radio coverage meant that they could not hear each other.

#### **1.10 Aerodrome information**

Not applicable.

#### **1.11 Flight recorders**

SHK has only examined recordings from the D-ACMI tool that is used to follow up and analyse military air combat operations and that utilises downloaded data from aircraft concerned, from the Gripen's mission support system for planning and debriefing (MSS) and from navigation applications. The aircraft's crash-protected memory units have not been recovered since the above recordings have been considered sufficient for the investigation.

##### ***1.11.1 Cockpit Voice Recorder***

The sound recording from the MSS system shows that the group leader for HAMMER informed his group members of the oncoming GUSTO two-ship by directing them to look up. This was done approximately 20 seconds before the passage.

SHK has not been able to gain access to GUSTO's sound recordings as these were no longer available when they were requested.

#### **1.12 Site of occurrence**

The incident occurred in the airspace north-west of Arvidsjaur, at position 6542N 01851E, 22 000 feet (6 650) metres above mean sea level.

**1.13 Medical and pathological information**

Nothing indicates that the mental and physical condition of the pilots were impaired before or during the flight.

**1.14 Fire**

Not applicable.

**1.15 Survival aspects**

Not applicable.

**1.16 Tests and research**

Not applicable.

**1.17 Organisational and management information**




Figure 21. Organisational chart for the exercise, ACE 17. Source: Armed Forces (Finland).

The ACE 17 organisation consisted of a staff and exercise participants (see Figure 21). The organisation is described in the Exercise Operation Order – EXOPORD.

The staff consisted of delegates from the three host nations, with Finland having the main responsibility.

The Exercise Director (EXDIR) is the highest person responsible for the management and steering of the exercise and for the exercise as a whole. He also has the mandate to abort or modify the exercise or parts of it if safety so requires.

Under the Exercise Director there are three Deputy Exercise Directors (DEP EXDIR) and also operational directors (DIR OPS – Director Operations).

The operational directors are responsible for the management and day-to-day direction of the staff and are to review the planning and provide direction and guidance to the staff as regards the implementation of the exercise. They are also to keep the Exercise Director informed of safety-related factors.

The flight safety organisation that is under the Exercise Director consists of a Chief of Safety and flight safety officers for each wing (WFSO – Wing Flight Safety Officer) and for each squadron (FSO).

An AIRBOSS with a staff from the three host countries is directly responsible for the exercise's planning and implementation.

It was part of the responsibility of AIRBOSS to coordinate the exercise with the Norwegian airspace centre in Reitan (NAOC) before and during the afternoon sessions that are composite aerial combat missions (COMAO<sup>21</sup>). AIRBOSS was also responsible for approving the separation plan (Deconfliction Plan) ahead of each sortie and for the participants being informed of the plan.

The Norwegian airspace centre together with a flight safety staff was responsible for the planning, drawing up and distribution of the Airspace Control Order (ACO) and the Air Tasking Order (ATO).

The active exercise participants, which consisted of flying units and tactical control and which were to be exercised daily, were led by a Mission Commander (MC) appointed each day for the blue and for the red forces.

The Mission Commander was responsible, among other things, for planning, briefing, implementation and debriefing of the missions. An important role was to draw up a separation plan in order to ensure a safe planning for separation, including during flight to and from the exercise area. The Mission Commander was to then inform AIRBOSS of the separation plan and have it approved by him.

### ***1.17.1 The exercise in general***

Interviews with the exercise management and the three countries' safety officers show that the afternoon's exercise was complex and that the details of the administrative flight phases<sup>22</sup> between different missions were presumably not entirely clear. The formal briefings were conducted in accordance with the planned time schedule. It has also emerged that some of the information was not presented in the briefings' presentation material but was only conveyed verbally.

---

<sup>21</sup> COMAO (Composite Air Operations).

<sup>22</sup> Administrative flight phases refer to air transport routes between different mission elements and combat areas and to and from the air bases.



According to interviews with the exercise management, neither was the procedure for the pilots' radio calls to get information about the nearest aircraft ahead of an altitude change (ELEVATOR CALL) entirely clear and could also deviate from national procedures. It was unclear if these radio calls were mandatory and whether they were dependent on whether visual or instrument meteorological conditions prevailed.

The briefing images for aerial combat (Offensive Counter Air – OCA) and ground attack missions (Strike) show that HAMMER and GUSTO were planned to be in the same area at a close point in time (see Figure 22).




Figure 22. Briefing images for aerial combat and ground attack missions (HAMMER and the push time for GUSTO are circled in purple). Source: Armed Forces (Sweden).

The images show that the blue forces were divided into two areas (lanes), west and east, that were demarcated by a line called BENO MSN (BENO Mission) which was not allowed to be crossed during the mission.

### 1.17.2 *The Mission Commander's (MC) workload*

The Military Flight Safety Inspectorate in Sweden (FLYGI) conducted a supervision of the exercise and drew up a report. In its report, FLYGI has written that the Mission Commander (MC) had an unreasonable responsibility. Several of those interviewed have also related that the Mission Commander had a high workload because the planning work for separation was complicated and extensive. In SHK's interviews with the Mission Commander, he has related that the planning work intensified after 18:00 hrs and was very intensive during the following morning.

### 1.17.3 *Principles for tactical control and flight information during the ACE exercise*

During the exercise, both in the combat area and for some of the administrative flight phases, a tactical control method called "Loose Advisory Control" was applied, which meant that the controller was only to provide traffic information upon request from the pilots.

Surveillance aircraft, including ASC 890, used Link 16, a data link system that, where necessary, provides information on flight position and status of other aircraft that are also connected to the system, and could thereby follow and link L16-equipped aircraft and generate own targets with the use of their own radar and IFF (Identification Friend or Foe).

During the afternoon session on 25 May, the US Navy's tactical control unit (TAOC EARTHQUAKE) had main control responsibility in the exercise area. At its disposal, it had primary radar and L16 in order to reconnoitre and follow flight operations, and radio for communication. As previously mentioned, the Mirage 2000 aircraft lacked L16 equipment and therefore could not be followed directly by means of the L16 system.

#### ***1.17.4 Changes within the airspace during the exercise***

According to interviews with the management staff for ACE 17, one of the exercise goals was to train the transition from a defensive war under attack to a more offensive behaviour that entailed a movement of the front line north. This resulted in a dynamic airspace with changes of important boundaries and safety lines during the course of the exercise. Two separate combat areas (east and west) also made possible parallel missions for the blue forces.

The design of the airspace as shown in the Airspace Control Order (ACO) was admittedly changed very little, but the tactical lines were changed from day to day by the Mission Commanders (MC) and their staffs.

#### ***1.17.5 Planning documentation for the blue forces.***

The afternoon session of the blue forces was planned and presented to the exercise participants by means of, among other things, a coordination card (Blue Coordination Card) and airspace images (see Figures 23–25).

Between the various blue forces was a separation line (BENO MSN) that separated the eastern and the western combat areas and that was not to be crossed. Information on the separation line was included on the coordination card and was there defined by means of coordinates and airborne alert for aerial combat (CAP – Combat Air Patrol), see Figure 23. However, that information was not shown in the airspace picture (Figure 25) that was presented during the briefings.

In addition to this, the coordination card also gives the coordinates of entry and exit points to and from the aerial refuelling area (Functions A–O in Figure 23) where point D was used by GUSTO in the transition from the aerial refuelling zone ROZ8 to the combat area (see also Figure 25).

ROUTE					AAR								
FUNCTION	NAME	LAT	LONG	REMARK	ROZ 7H : TEXACO @ 25k			ROZ 8H : SHELL @ 26k			ROZ 9H : COBO @ 26k		
BULLSEYE	GÄLLIVARE	N6708	E2048	MAGV 7	SLOT	CS	OFFL	SLOT	CS	OFFL	SLOT	CS	OFFL
BENO 1		N682223	E0195719	BLUE LO	1255-1315	JAKAL01	20K	1200-10	BOW57	10K	1215-35	PANTR21	16K
BENO 1		N664983	E0219937	BLUE LO	1225-45	JAKAL05	20K	1210-25	STORK51	20K	1315-35	STEEL21	16K
BENO 1		N661844	E0235756	BLUE LO	1205-25	FANG 11	20K	1245-55	GUSTO55	10K		VERMIN15	
HOLD EAST		N653500	E0203100	040°							1255-1315	DALTON5	20K
HOLD CTR		N660000	E0192000	040°							1235-45	DALTON35	10K
HOLD WEST		N662200	E0181900	040°								PANTR25	
LL BENO		N6714	E02305									GATOR21	
LL BENO		N6550	E02010									GOLD25	
BENO MSN		N6535	E01850		FUNCTION	NAME	LAT	LONG	REMARK				
BENO MSN		N6630	E02009		A		N6625	E01650					
BENO MSN		N6707	E02047		B		N6603	E01715					
CAP W1	BL 22-24(1)	N6705	E01810	045°	C		N6550	E01755					
CAP W2	BL 22-24(2)	N6654	E01953	060°	D		N6539	E01833					
CAP E1	L 31-34(30)	N6640	E02100	360°	E		N6525	E01914					
CAP E2	L 22-24 (2)	N6640	E02230	030°	F		N6514	E01950					
PUSH W OCA	BACK CAPE	N6635	E01845	OCA	G		N6505	E02031					
PUSHE OCA	BACK CAPE	N6565	E02037	OCA	O		N6532	N01517					

Figure 23. Coordination card for the blue forces (Blue Coordination card) with coordinates for airspace division with separation line (BENO MSN), entry and exit points for aerial refuelling and holding patterns for aerial combat (CAP). Source: Armed Forces (Sweden).




Figure 24. Map documentation from the Airspace Control Order for mass briefing of the exercise participants (PM mission day 4, 25 May CH3). Source: Armed Forces (Sweden).




Figure 25. Coordination card with map documentation for the afternoon session of the blue forces (Blue Coordination card) with aerial refuelling zones and entry and exit points for these. Source: Armed Forces (Sweden).

### 1.17.6 Principles for separation

During ACE 17, there were just over 100 aircraft that were located in the same airspace and that took off and landed at three different bases. The exercise management considered it a complex challenge to separate the units in a safe and clear manner.

The airspace division and the separation rules were established by the exercise's operation order (EXOPORD) and were supplemented with special instructions called SPINS (Special Instructions). In addition to this are the generally accepted rules for altitude separation between aircraft, which normally entail a vertical separation of 1 000 feet.

The following is shown in NATO's manual 75-2-1<sup>23</sup> regarding exercise rules for aerial combat:

Fighters may not transit or enter the altitude/altitude block of any adversary unless at least one of the following conditions is met:

- (1) Fighter is beyond 10 NM with all adversaries entering the engagement.

<sup>23</sup> Allied Command Europe Manual 75-2-1, Fighting Edge Air-to-Air Training Rules, 23 February 2011.

(2) Adversary is within 10 NM, but not a factor (i.e. no potential collision) based on situational awareness, geography, timing, on-board systems, GCI/AEW, visual contact, other fighters, or any other appropriate aid.

(3) Visual contact is established.

(4) Fighter verbally confirms adversary's hard altitude direct with the adversary and maintains 1 000 feet vertical separation.

The most common method for separating military aircraft is to define different altitude blocks for different groups and missions.

The principle for separation is shown in Figure 26. The airspace has been divided up into five different blocks in which separation between red and blue units is defined. At low altitude, the terrain is also taken into account. These blocks are necessary since the tactical control has a passive role and the position of the opposing forces is intentionally not known.

In addition to the blocks are limited areas (with a centre point and a defined radius) in which aircraft can change altitude between the blocks in order to carry out missions such as aerial refuelling, holding pattern or reassembly for combat (REGEN) in a specific area.

Another method for separation is time separation. Different groups receive different times for specified coordinates or phases in the combat. These times are planned in order to avoid collision risks. SHK has not found any information that the separation planning has been tested through simulation before implementation.

Within the same block, "Lanes" for units from the same force (blue or red) can also be defined in order to facilitate more parallel missions within the same altitude block at the same time. Such "Lanes" can be separated by means of a BENO MSN line.

It is also apparent from SPINS that the flying units may change altitude in real time based on their own situation awareness (SA), which can be obtained by means of their own sensors, ELEVATOR information from the tactical control or in other ways, such as visual information.




Figure 26. The principle for separation during ACE 17 by means of altitude blocks. Source: Armed Forces (Finland).

### 1.17.7 Operational Risk management Method (ORM)

Prior to each exercise, the Swedish and Finnish air forces performed risk analyses specifically for ACE 17. The risk analyses followed an approved methodology entailing evaluation of the risks through comparing the consequence of a specific event with its probability. The method is based on the risks being assessed in a table with the consequences in the Y axis (from negligible to catastrophic) and the probabilities in the X axis (from unlikely to likely). Combinations of catastrophic likely events (marked in red fields) may not occur, and measures must be taken to reduce the probability or consequences (see Figure 27).



### Risk Assessment Matrix

RISK ASSESSMENT MATRIX (OPNAVINST 3500_29C)			Probability Categories			
			Unlikely To Occur	May Occur	Probably Will Occur	Likely To Occur
			A	B	C	D
Hazard Severity Categories	NEGLIGIBLE Minimal threat to safety or the Efficient use of assets	I	1	1	2	3
	MARGINAL Minor injury, Degradation to Efficient use of assets	II	1	2	3	4
	CRITICAL Severe injury, damage Or degradation to Efficient Use of assets	III	2	3	4	5
	CATASTROPHIC Death or loss of asset	IV	3	4	5	5



18. lammikuu 2017

Figure 27. Risk assessment matrix – the consequence of the risks in relation to their probability. Source: Armed Forces (Finland).

As a part of the safety work ahead of the exercise, the safety organisation identified and categorised the various risks according to the method above. The risk analysis was common to the flight operational and tactical control units.

Some of the risks that concerned the incident in question were captured and analysed and were assessed to be acceptable for the exercise. Besides this, measures were taken to reduce the effects or probabilities of these events.

By way of example, it can be mentioned that the risks of altitude deviations, collisions in the air and radio interference were included in the analysis (see Figures 28 and 29).

**Flight Operations, OPS**

Exercise: ACE 2017 Flight operations

Hazard (Consequences)	Causes	RA	Corrective Actions, Responsible for actions and Deadline	LRA
Block violation, collision in air	<ul style="list-style-type: none"> <li>Serious A/C malfunction during operation</li> <li>Weak or incorrect SA on other players</li> <li>Lots of A/C</li> <li>Superimposing during fight</li> </ul>	IV/B-4	<ul style="list-style-type: none"> <li>All players should use same regulations during exercise: Fighting Edge</li> <li>Plan what shall an A/C with malfunction do: Inform other players 121.5, possible emergency descent, posit</li> <li>List (picture) of suitable fields for emergency landing for all players (field, position, freq, length...)</li> <li>Visual (Incl. arresting cable) can be used as an emergency field only (middle of training area)</li> <li>During brief stress the fact that your SA might not be correct - "What is your SA?" (Human Factors)</li> </ul> <p>Time: Before and during exercise Responsible: AB, MC, OPS, UCI and pilots</p>	IV/A-3
Collision in air	<ul style="list-style-type: none"> <li>Weak or incorrect SA on other players</li> <li>Low knowledge on how other type A/C maneuver (specially WVR fight)</li> <li>Differently maneuvering A/C, high AOA</li> </ul>	IV/B-4	<ul style="list-style-type: none"> <li>Every pilot should acknowledge that the air picture/SA can be inaccurate</li> <li>Brief how different A/C maneuver in WVR, low knowledge on how other type A/C maneuver</li> </ul> <p>Time: During exercise Responsible: Instructors and pilots</p>	IV/A-3

Figure 28. Identified risks regarding altitude deviations and collision in the air with measures to reduce the risks. Source: Armed Forces (Finland).

C2 EAGLE		KALLAX		
Exercise: ACE 2017				
Hazard (Consequences)	Causes	RA	Corrective Actions, Responsible for actions and Deadline	LRA
Commsjamming might effect the flightsafety	FC might be unable to read out essential information.  Commsjamming will not be executed from CRC (will be done from an aircraft).	IIID-4	- The methods for cease jamming are described in SPINS. - C2 personel participating in the mission planning will highlight the cease jamming methods with aircrws. Communication channels not alod to be jammed must be defined in the planning phase.	IIA-1
Civilian medical traffic penetrates the exercise area	Medical flights might need to fly through the restricted area.	IIID-5	To be read in SPINS and highlighted on the mandatory inbrief: • If civilian traffic penetrates the exercise area, GCI/ACI will activate a hardfloor either within a defined ROZ or in the whole exercise area. It's the pilot in commands responsibility to keep separation to the temporary traffic ROZ or the hardfloor of the exercisearea.	IID-4

Figure 29. Identified risks regarding radio interference with measures to reduce the risks. Source: Armed Forces (Finland).

## 1.18 Additional information

### 1.18.1 Actions taken

#### *The ACE 17 organisation*

The exercise management has published a final report called Final Exercise Report (FER) for ACE 17. The report encompasses an evaluation of the exercise, but not specifically of the incident now in question. The following is a summary of the recommendations in the report:

- During planning conferences, the challenging nature of VTC planning and operations in a high-risk environment should be emphasized.
- For future exercises, it is tactically preferable that fast jets participating in the exercise have L16 capability.
- ATO must be timely available on Squadron level so that ambitious timelines shall not be corrupted. The admin process of the ATO has to be reviewed and improved (printing, CD burning).
- For the next ACE there should be a standing ACO for the DCA days and after that a second one for the remainder of the exercise (OCA phase). This will enable the participating forces to concentrate on tactical elements of the sortie to maximize training value for all participants, also to improve flight safety.



- At the beginning of the exercise, it is important to have an experienced MC run the first planning session and have all the necessary materials available for planning.
- There needs to be Positive Control<sup>24</sup> available in future exercises. The related problems have been identified, and measures aimed at overcoming this problem have already been initiated for ACE 19.
- TAOC Integration to C2 was a challenge due to the technical difficulties in the first period of the exercise. In future ACE exercises, new controlling systems which operate in Swedish airspace must be evaluated before the exercise starts.

#### *The Swedish Armed Forces*

The Swedish Armed Forces has investigated the incident in question and has made the following recommendations in its report “Simplified investigation ACE 17”:

*R1 Same ACO throughout the exercise period.*

*R2 ACO should to a large degree manage flight paths and altitudes between*

- *Bases and the exercise area*
- *Aerial refuelling and holding area*

*R3 FSL<sup>25</sup> should be given power to control aircraft (CLOSE ADVISORY CONTROL) in the area when FSL considers it appropriate.*

*R4 Ensure radio and radar coverage in the flight safety-critical areas, such as AAR, TRANSIT CORRIDOR and HOLDING AREA.*

#### *FLYGI (Military Flight Safety Inspectorate)*

FLYGI has reviewed the exercise, but not specifically the incident in question, as part of its supervisory tasks. The following is shown in “FLYGI report after supervision of exercise ACE 2017” regarding forthcoming exercises:

*Ahead of forthcoming exercises of this character with a large number of aircraft from many nations and sometimes with an exercise management that has significant elements from other nations, it is important from the perspective of FLYGI that the exercise planning is integrated more between designated exercise management and the central operator managements including the central flight safety function. The new process for exercise planning should be promptly established and implemented in accordance with the Supreme*

<sup>24</sup> Positive Control – Fighter controller is responsible for collision avoidance, ie. restrict or control aircraft to maintain separation. This flight safety method is the one normally used in controlled airspace.

<sup>25</sup> FSL – Fighter Controller.

*Commander's (ÖB) decision. The perceived pressure on the organisation to increase operational effect, as well as the task of cooperating with other nations, mean that the work and the follow-up of a sound flight safety culture becomes especially important.*

**1.19 Special methods of investigation**

Not applicable.

## 2. ANALYSIS

The analysis discusses the serious incident involving a near collision that occurred on 25 May 2017 between Swedish and French fighter aircraft during the international military exercise ACE 17 in the air-space north-west of Arvidsjaur. The Swedish aircraft consisted of a four-ship of JAS Gripen, with the call sign HAMMER, while the French aircraft consisted of a two-ship of Mirage 2000 with the call sign GUSTO.

### 2.1 Introduction

The purpose of the analysis is to create a logical connection between the factual information and the conclusions in order to provide answers to why the incident occurred, as well as which events and conditions have contributed to the incident.

The delimitations that have been presented in the report's introduction also apply to the report's analysis section. The analysis therefore does not discuss general national regulations for the armed forces concerned, the activities and planning of the red forces or the US Navy's tactical control unit (TAOC).

### 2.2 The exercise ACE 17

The event occurred during the international military exercise ACE 17 (Arctic Challenge Exercise 2017) that took place in the northern part of Finland, Norway and Sweden. It was the third time the exercise was conducted. During ACE 17, more than 100 aircraft participated from more than ten countries as well as ground units for tactical control and support, among others. The exercise was multinational and aimed to practise and train these units in a dynamic and credible environment.

The objective of ACE 17 was also for pilots from several nations to conduct joint exercises with different aircraft types in large composite air forces in which tactics and procedures are practised in a realistic threat environment with simulated anti-aircraft systems. The fighter aircraft that participated proceeded from Luleå in Sweden, Rovaniemi in Finland and Bodø in Norway.

An exercise of this scope is complex and places great demands on planning, coordination and control.

Besides this, the Nordic countries have for many years conducted joint exercises in the same area as part of a cooperation called Cross Border Training. Despite this, it is a major challenge to conduct exercises of this kind, particularly considering the fact that there might be cultural aspects and certain language barriers that can lead to varying perceptions regarding the interpretation of common exercise rules and briefings.

## 2.3 Preconditions

### 2.3.1 *Planning and preparations in general*

The planning for the exercise was commenced at the beginning of the year with exercise conferences to lay the foundations for the exercise and to secure experience from previous ACE exercises that were conducted in 2013 and 2015. SHK notes that there were thereby good conditions and plenty of time for the ACE 17 organisation to perform an adequate planning of the exercise in general.

The tactical control in the respective countries controlled the aircraft to and from the exercise area. Within the combat areas themselves there was only information service, called “Loose Advisory Control”, which means that the pilots themselves had responsibility for maintaining their own separation in relation to the exercise area’s lateral and vertical boundaries and to other military aircraft that were participating in the exercise. The pilots also had opportunity, where necessary, to request information about other traffic from the tactical control. The separation between the aircraft was based on pre-planning in time and space in accordance with a separation plan called “Deconfliction Plan”.

SHK is of the view that “Loose Advisory Control” places great demands both on a detailed and precise pre-planning of the separation plans in time and space, particularly as the combat scenarios change from day to day during the course of the exercise, and also for the separation plans to be communicated with the exercise participants in a clear and structured manner. There is therefore cause to address in more detail how this was conducted.

The separation plans consist in principle of ACO (Airspace Control Order), ATO (Air Tasking Order) and Coordination card.

### 2.3.2 *ACO and ATO*

The defining of the airspace’s demarcations, with restriction areas and specific corridors, was carried out by a working group called AWG (Airspace Working Group), and was communicated to the participants in the form of a control order for the airspace called ACO (Airspace Control Order). The same working group also issued the Air Tasking Order called ATO. ACO and ATO were to be distributed to the participants at 13:00 hrs the day before the afternoon exercise (PM Wave). However, according to interview information, there were some delays in the distribution.

SHK has noted that ACO and ATO only covered basic information about the airspace and the combat missions. This meant that an extensive planning work remained for the specially designated persons (MC – Mission Commander and Airboss) with associated staff who had the task of performing the detailed planning for the entire PM Wave. Besides this, the late distribution limited the available planning time.

Since the participants proceeded from the three bases Luleå, Rovaniemi and Bodø, the various briefing steps were conducted via video teleconference (VTC). This made it possible for all those concerned to participate. At the same time, one should be aware that such a solution places high demands on the participants since a direct interaction does not come as naturally as in the case of a physical meeting. It is also possible that the VTC environment, which places high demands on a disciplined behaviour, can contribute to the absence of spontaneous questions.

### **2.3.3 *The detailed planning for the blue forces***

The detailed planning for the blue forces ahead of PM Wave was compiled and presented to the participants in the form of a coordination card called “Blue Coordination Card”, which is a part of the separation plan.

The card shows that the HAMMER four-ship had the same altitude blocks during the entire session (22 000–24 000 feet), while GUSTO was to conclude the aerial refuelling procedure at 27 000 feet to then carry out a ground attack mission at 16 000 feet. It is furthermore apparent that HAMMER was to conclude its combat mission at 13:00 hrs UTC (15:00 local time) to then return to Luleå. At the same time, GUSTO was to conclude the aerial refuelling at 12:55 hrs UTC (14:55 local time) and fly on to its holding pattern in order to reach the departure point for the ground attack mission at 13:09 hrs UTC (15:09 local time).

It is also apparent from the briefing images (see Figure 22) that both groups were to be located in the same area at around the same time.

This means that already in the planning stage there was a potential conflict in time and altitude between HAMMER and GUSTO in around the same area, which according to SHK shows that there were deficiencies in the separation plan.

## **2.4 The near collision incident**

The Swedish four-ship consisted of four members designated HAMMER 11, 12, 13 and 14. In connection with the near collision incident, the group was in a trail formation in the order HAMMER 11, 13, 12, 14, in which HAMMER 11 and 13 formed a two-ship.

The French group consisted of two members designated GUSTO 55 and 56 and had a two-ship formation in which GUSTO 55 was leading the formation and had GUSTO 56 on its right side.

#### **2.4.1 *General preconditions***

In connection with the near collision incident, visibility was good. There were no clouds at the altitudes in question. Since the exercise was conducted with “Loose Advisory Control”, the pilots were responsible for the separation in relation to other aircraft.

Under the given conditions, the separation can be achieved in different ways. Visual separation is based on the pilot visually discovering and avoiding other aircraft. Besides this, the pilots can make use of on-board systems, such as radar and data link L16 and request information from the tactical control through special calls called “ELEVATOR call” in order to improve their own position picture in relation to other aircraft.

Situation awareness (SA) is often used as a term regarding the pilot’s own perception of where he is located, usually based on the visual impression, sensor information, radio communications or a picture of the surroundings that has been created over time. This is then to be related to combat targets and a future picture of how the situation will change.

The term SA also occurred in connection with the exercise ACE 17 as one of several possible ways of ensuring adequate separation in relation to the adversary’s aircraft. However, the term is only intended to be applied in connection with aerial combat (Fighting Edge), as shown in section 1.17.5.

SHK considers it doubtful whether it is possible to maintain an acceptable level of SA in connection with loss or absence of sensors such as on-board radar and L16. This particularly applies in situations where the radio communication is not functioning satisfactorily.

#### **2.4.2 *The sequence of events according to recorded data***

The sequence of events was reported immediately after the session by the pilots based on their own visual estimates of the distance between the aircraft. The pilots discovered each other late and estimated the lateral distance to be very close or between 100 and 300 metres.

SHK has also examined the measured passage as it was recorded by position data that was downloaded from the respective aircraft’s memory unit and where the sequence was recreated by a debriefing system called D-ACMI. Through the simulation it was possible to measure the minimum distance between GUSTO 55 and HAMMER 12 to be 150 metres laterally and 30 metres vertically.

The measurement accuracy regarding the aircraft's navigation position is dependent on the navigation system itself on board each aircraft. The Gripen aircraft are equipped with a combined inertial platform (INS) and a GPS receiver, which normally gives small position errors. The Mirage aircraft are equipped with an inertial platform (INS) that gives the position but, among other things, contains an inherent position error that grows with time (integration drift) which can amount to approximately 600–900 metres per hour (counted from the start-up time for the system). SHK cannot subsequently assess the size of the navigation error that the inertial navigation system had during the passage and has therefore also examined other sources in order to estimate the distance.

LFV's WAM system consists of surveillance sensors by means of which an aircraft's position is determined via triangulation, which entails measuring the time difference between responses to a number of receiving stations on the ground. The principle is the same as for normal mobile phones whereby location is done by means of triangulation.

The accuracy in WAM is higher than in traditional radar and provides coverage in places in Sweden where there has not previously been any coverage or where the coverage has been poor. The WAM system had good signal coverage in the area in which the incident occurred, and it has been possible to analyse the relevant distances. Based on the analysis of WAM data, it was possible to estimate the distance between the closest GUSTO and HAMMER aircraft to be approximately 150 metres laterally.

Besides this, SHK has examined transponder data from the aircraft from the time of the incident. By means of these data, the distance between GUSTO 55 and HAMMER 12 can be estimated to be 480 metres during the passage.

From compiled data and interview information, SHK is able to draw the conclusion that the passage was so close that it constituted a collision risk and that the late discovery entailed that the passage was not controlled in terms of separation.

#### **2.4.3 *The event from the perspective of HAMMER***

According to the briefing documentation and interviews with the Gripen pilots, the HAMMER group had just concluded an aerial combat mission in the western part of the combat area and was in the process of reassembling the group ahead of egress to Luleå.

According to the interviews, the group leader's intention was to leave the combat area south and turn east towards the eastern transit corridor when they had passed the southern end of the separation line BENO MSN.

From the briefing material, SHK is able to note that such a line existed and that it extended south towards the aerial refuelling area. Based on the interviews and the combat planning, it is also possible to assume that BENO MSN was a line that separated parallel blue missions in two different areas (eastern and western “lanes”) and that the line was not allowed to be passed.

Gripen’s digital map (see Figure 11) shows the BENO MSN line in red (in the centre of the map) and the planned route for the flight home in blue. These confirm HAMMER’s intention to continue south and turn east, where the separation line ends.

SHK has noted that some of the ACO/ATO lines were missing on HAMMER’s flight map. The restriction areas for aerial refuelling and the transit corridors south of these were missing. According to the interviews, the Gripen team believed that that these did not concern HAMMER’s mission and therefore chose not to include these lines on the map.

SHK believes that the absence of restriction areas on HAMMER’s electronic map constituted a possible flight safety risk since the map did not make the pilots aware that they could come right next to the aerial refuelling operations and to aircraft en route into or out of these areas (see Figure 25).

SHK has also not been able to find more detailed routes for egress in the briefing material or ACO/ATO. Together with the lack of information in HAMMER’s digital map, this can explain the chosen route during the egress that went through a corridor-like area south of BENO MSN.

Due to the nature of the mission, the group was dispersed and was flying in a long trail in which the relative position of the members could be monitored by means of their own radar and data link information (see Figure 11). During the incident, HAMMER 11 and 13 had already joined a close tactical formation, while HAMMER 12 and 14 were following the first two-ship at a distance, with HAMMER 12 being third a few nautical miles after the two-ship and HAMMER 14 a few more nautical miles further back. The group maintained the allocated altitude of 22 000 feet.

According to interview information, HAMMER 11 followed the GUSTO two-ship by means of its radar shortly before the incident and noted that the two-ship was beginning to descend and was approaching HAMMER’s own altitude. HAMMER 11 discovered GUSTO visually by means of its helmet display (HMD) and had time to inform the other group members via radio. The radio call was transmitted on the HAMMER frequency and therefore could not be heard by GUSTO.



SHK has listened to the radio recording (on Gripen MSS) but does not find that the radio call was sufficiently detailed to help HAMMER 12 or 14 to localise the GUSTO two-ship. Hammer 14 obtained visual contact with GUSTO, which passed him at a much lower altitude, and continued the connection to the rest of the group.

SHK therefore draws the conclusion that there was a high collision risk and that there was not sufficient time to perform an evasive manoeuvre.

#### **2.4.4 *The event from the perspective of GUSTO***

According to the briefing documentation and interviews with the Mirage pilots, the GUSTO group had just concluded the aerial refuelling in the central area (ROZ8) and was en route back to the combat area in order to carry out an attack mission.

The time coordination card shows that GUSTO was to descend to 16 000 feet in order to be able to begin the attack from the PUSH point at the right altitude after the aerial refuelling, which was conducted at a higher altitude.

The interviews show that GUSTO 55's radar was temporarily inoperative at the time of the incident, while GUSTO 56 had its radar in standby mode so as not to disturb the two-ship leader. Despite this, it is apparent from interviews that the two-ship leader considered himself to have a good situation awareness (SA) based on his perceived picture of the situation. GUSTO chose to change altitude without succeeding in getting traffic information from the tactical control, which was permitted according to the exercise rules regarding ELEVATOR CALL under visual conditions.

The recordings of the radio communications show that GUSTO 55, as an extra measure, requested information on the aerial refuelling radio channel concerning nearby aircraft according to the ELEVATOR procedure, but never perceived any response from the tactical control. After several attempts to obtain contact with the tactical control, GUSTO changed frequency to the secondary frequency and reported on this frequency about one minute after the incident.

The digital map for Mirage (see Figure 12) shows a corridor (drawn with orange-coloured lines) from the aerial refuelling area to the combat area and past holding pattern CENTRE. The planned route to the attack target appears in blue with the navigation points 14 to 18. These confirm GUSTO's intention to fly according to the route and descend in order to be at the right altitude ahead of the attack mission. Also seen are the exit points E, F and G, while point D is presumably hidden underneath the text ACE RBFA. The coordinates for point D, as shown in the briefing material and the coordination card, can be considered to be a logical exit point from the central aerial refuelling area north.

SHK has noted that some of the lines on the Mirage map were missing and that some lines were found only on this map. BENO MSN, which divided the combat area, was missing on the map, whilst it has not been possible to trace the orange-coloured corridor towards HOLD CENTRE (between the navigation points 14 and 15) back to the exercise planning documentation.

According to the interviews, GUSTO considered the chosen route to be correct and this was also confirmed verbally during the planning in connection with a meeting with MC before the flight.

GUSTO's planning and the implementation of the transition between the aerial refuelling and the attack mission were in line with the information in the on-board digital map.

However, the discrepancies between the formal briefing material and the digital map resulted in GUSTO descending through altitude blocks and areas that were also intended for other exercise participants, which resulted in a risk of separation infringement in relation to other aircraft and thereby a possible collision risk. This risk would probably have been dealt with if GUSTO had had an active radar.

The frequency changes that were made by GUSTO's group leader in connection with the altitude change might have contributed to him partly focusing on the aircraft's radio panel at the same time as the two-ship wingman was focusing on the two-ship leader.

In summary, SHK believes that there were several circumstances that impeded GUSTO's opportunities to have an adequate situation awareness in connection with the event.

#### **2.4.5 *The event from the perspective of the tactical control***

It is clearly stated in special instructions (SPINS) for the exercise that the "Loose Advisory Control" principle applied to all the control units during PM Wave. This means that the tactical control was not controlling the traffic in a traditional manner, but only had the role of information source if airborne units made specific calls. The instructions emphasise the pilots' strict responsibility for the separation between the aircraft, both in the exercise area and during transitions to and from the combat area.

As shown by ACO and ATO for the applicable time period, TAOC with the call sign EARTHQUAKE had the main control responsibility for traffic information in the case of calls from the participants during the event. In the combat areas in question, CRC EAGLE had the role of backup on the frequencies. In addition to these, the reconnaissance aircraft ASC 890 had a secondary role to follow and compile the data link communication (L16) and monitor the northern part of the combat area.

Interviews with several members of CRC EAGLE and review of CRC recordings and the unit's formal report show that the CRC EAGLE operators were aware of the collision risk that developed shortly before the passage, but assumed that the aircraft had visual contact with each other and therefore did not take any action.

The recordings also show that the reception regarding the radio traffic from EARTHQUAKE was intermittent and that other means of communication with TAOC had certain deficiencies.

SHK notes that CRC EAGLE acted in accordance with the instructions in SPINS regarding the division of responsibility between the tactical control and the pilots as regards the separation. EAGLE's assumption that GUSTO had visual contact with HAMMER was understandable under the prevailing circumstances and weather conditions.

## **2.5 Organisation and management**

The exercise's organisation and management have previously been described in the introduction of section 1.17. SHK notes that the structure of the organisation follows the description shown in the operation order for the exercise, called Exercise Operation Order (EXOPORD).

### **2.5.1 *The exercise in general***

Interviews with the exercise management and safety officers have shown that the exercise was complex and that the details of the administrative flight phases (air transport routes between combat missions) between different missions were not entirely clear. It has also emerged that the procedure to change altitude, called ELEVATOR, was not entirely clear. The ambiguities consisted in it being unclear if radio calls were mandatory and if these were dependent on the meteorological conditions (IMC/VMC). It has also emerged that there were different perceptions regarding corridors and demarcation lines, "BENO lines".

SHK believes that an exercise of the size now in question, with many participants from many different countries, places very high demands on the exercise management to ensure that administrative flight phases and altitude change procedures are described and explained to all participants in a clear and unambiguous manner. The ambiguities have probably been due to the fact that the Airspace Control Order (ACO) was changed from day to day and to its not containing sufficiently detailed information in this regard.

### 2.5.2 *MC's workload*

Several of the persons that SHK has interviewed have stated that they considered MC to have a high workload because the planning work for separation was complicated and extensive. FLYGI (Military Flight Safety Inspectorate) has drawn up a supervision report regarding the exercise. In the report, FLYGI notes that MC had an unreasonable responsibility. In SHK's interview, MC related that the work was very intensive and extensive.

SHK believes that the exercise's complexity and scope make it necessary to relieve MC's planning by integrating as much information as possible in the Airspace Control Order (ACO) and in the Air Tasking Order (ATO), particularly with regard to separation and transit corridors.

### 2.5.3 *Principles for tactical control and flight information*

During the exercise, the "Loose Advisory Control" principle was applied for some of the administrative flight phases and for the combat area. Besides this, Link 16 was used in order to be able to follow L16-equipped aircraft. However, GUSTO was not equipped with this system.

SHK's view is that the exercise management should consider whether it is necessary to exercise Positive Control during a greater part of the administrative flight phases. Furthermore, SHK believes that there is a need to streamline the use of data link systems in order to make information available to more participating units.

### 2.5.4 *Planning of airspace changes during the exercise*

The Airspace Control Order (ACO) was changed from day to day during the course of the exercise. It was necessary for some changes of this kind to take place with reference to the exercise's complexity, dynamics and scope.

Admittedly, ACO for PM Wave did contain certain transit corridors, aerial refuelling areas and demarcating lines. However, there was no information on how the transition from the aerial refuelling area to the combat area was to be conducted, nor on how the transition from the combat area to the transit corridors published in ACO was to be conducted.

This resulted in MC with associated staff, in addition to the tactical planning, also having to plan some of the administrative flight phases.

SHK believes that the exercise management did not utilise all existing opportunities as regards creating an ACO with as few changes as possible from day to day and with more detailed information for procedures for some of the administrative flight phases.

### 2.5.5 *Principles for separation*

It is a complex task to separate aircraft in a safe and clear manner in a major exercise with just over 100 participating aircraft. This can, among other things, be resolved with different altitude blocks for different groups and missions, and with time separation.

SHK has not found any information that the separation planning was tested through simulation before the exercise was implemented and believes that the exercise management should consider the opportunities for introducing such a solution.

During certain phases of the exercise it was necessary to change altitude, e.g. in connection with aerial refuelling. Altitude change could be made based on situation awareness (SA) or after having requested flight information through the ELEVATOR procedure.

Situation awareness (SA) as a term is often used as a term for the pilot's self-perception of where he is located, usually based on the visual impression, the sensor information, the radio traffic or a picture of the surroundings created over a period. This is then to be related to the planned intentions and the future prediction of how the situation will change.

SHK has not found any clear and uniform description in the exercise material of what the term SA entails. Interviews have shown that the term was interpreted differently by the exercise participants. SHK believes that if the term SA is to be used in order to achieve adequate separation, the term is to be defined and explained to all participants ahead of the exercise so that it is interpreted in a uniform manner.

Performing an altitude change only based on one's own perception of the situation and without support from sensor data or confirmation from another source is assessed by SHK to constitute an unnecessarily increased collision risk.

The ELEVATOR procedure is clearly described in SPINS and assumes that the pilots have situation awareness (SA) regarding their own force (blue in this case). Information referring to their own force is therefore not included in the traffic information in ELEVATOR, unless this is specifically requested.

Since GUSTO requested traffic information (ELEVATOR) without specifically requesting information in relation to its own force, a response from the tactical control would probably not have contained any information on HAMMER.

### **2.5.6 Operational risk management method (ORM)**

Prior to the exercises of ACE 17, the Swedish and Finnish air force carried out risk analyses that were common to the air-operational and the tactical control units.

The risk analyses followed an approved method (the so-called Operational Risk Management method – ORM), which evaluates the risks by comparing how serious the consequences of a particular event might be, with the likelihood for the specific event to occur.

Certain safety risks were identified and assessed to be acceptable. Regarding other risks, measures were taken to reduce the effects or probabilities of these risks. Among others, the risks of altitude deviations, collisions in the air and radio interference were included in the risk analysis.

Making a risk analysis does not mean that risks are completely eliminated. On the other hand, it increases possibility of detecting and managing different risks, which reduces the likelihood and consequences of incidents and accidents. SHK believes, however, that there could be a safety-promoting effect if all countries that organise the exercise participate in a joint risk analysis (ORM).

### **2.6 Actions taken after the event**

The event was reported by GUSTO, HAMMER and EAGLE and was discussed during debriefing the same day.

SHK has not found any information that shows that the exercise management took immediate action after the event in order to prevent similar separation infringements and thereby increase flight safety during the remainder of the current day's exercise.

### **2.7 Overall assessment of the event**

The event in question was a near collision incident in which, under the prevailing circumstances, there was a high probability that an accident would occur.

The incident occurred in connection with administrative flight phases where HAMMER was en route to its home base and where GUSTO was en route to the combat area after aerial refuelling.

Both HAMMER and GUSTO considered themselves to be correctly following the instructions that they had received.

There were no established separation procedures according to the Air-space Control Order (ACO) for how the transition from the aerial refuelling area to the combat area was to be conducted. There were also no established separation procedures for how the transition from the combat area to the transit corridors published in ACO was to be conducted.

The responsibility for establishing these separation procedures therefore rested with the Mission Commander (MC), while Airboss was responsible for approving these. These tasks were to be performed within a very narrow time frame and subsequently presented to all participants via the video teleconference system (VTC).

The exercise management had capability to establish procedures for flight between the three air bases and the waypoints in the published corridors that surrounded the exercise area. The same applies to the procedures within the restriction zones for aerial refuelling. According to SHK, this indicates that the exercise management also had capability to establish clear and safe procedures for flight to and from the combat area and the aerial refuelling areas. The absence of such procedures was a factor contributing to the serious incident.

SHK believes this constituted a fundamental flight safety risk in the planning work ahead of ACE 17. These deficiencies are particularly apparent, firstly, because experience has been gained from two previous exercises of this nature in the same area and secondly, because the time to prepare and plan the exercise has been ample.

### 3. CONCLUSIONS

#### 3.1 Findings

- a) The pilots were qualified to perform the flights.
- b) The aircraft had no technical deficiencies that prevented the flights.
- c) In connection with the event, the radar sensor on GUSTO 55 was temporarily inoperative, while the radar sensor on GUSTO 56 was intentionally set to standby mode.
- d) The incident occurred in daylight with visual meteorological conditions and good visibility.
- e) The planning for the ACE 17 exercise was commenced in good time.
- f) The exercise management had access to lessons learned from previous ACE exercises in 2013 and 2015.
- g) The exercise management applied the tactical control principle “Loose Advisory Control”, which meant that the pilots were responsible for the separation.
- h) ACO and ATO were changed daily, were drawn up in time, but were distributed to the flying units with some delays.
- i) Work with planning and separation ahead of PM Wave entailed a high workload for MC.
- j) The separation plan (Deconfliction Plan) for PM Wave on 25 May, which was approved by the AIRBOSS, was not complete and resulted in risks of separation infringement between the flying units around the time of the incident.
- k) SHK has not found any information in the Mass Brief documentation regarding certain safety-critical details such as procedures and routes for transition between aerial refuelling and combat missions, and between combat missions and egress for the return to base.
- l) The VTC system that was used for planning and briefing might have limited the inclination to pose questions and develop discussions.
- m) HAMMER’s and GUSTO’s digital maps exhibited differences that entailed that each group had different pictures of the situation.



- n) HAMMER's digital map showed that the pre-planned route during the egress went through a corridor-like area that was not defined as a transit corridor in ACO.
- o) HAMMER's digital map lacked information on the aerial refuelling areas.
- p) GUSTO's digital map showed that the pre-planned route during the transition from the aerial refuelling area to the combat area followed a corridor-like area that was not defined as a transit corridor in ACO for the PM Wave.
- q) GUSTO called the tactical control and requested traffic information (ELEVATOR CALL) before the altitude change without receiving a clear response. According to the exercise rules, it was permitted to change altitude without traffic information under visual conditions.
- r) GUSTO changed altitude based only on its own situation awareness (SA), which was based on the perceived traffic situation. During the incident, sensor information to contribute to SA was lacking.
- s) The passage between GUSTO 55 and HAMMER 12 was uncontrolled and entailed an immediate collision risk.
- t) It was not clearly defined what was meant by a good situation awareness (SA), even though this was a condition for the altitude change procedure (ELEVATOR).
- u) A joint operational risk management method was used only by the Swedish and Finnish air forces.

## **3.2 Causes and Contributing Factors**

### **3.2.1 Causes**

The cause of the event was that the exercise management underestimated the risks of separation infringement during the administrative flight phases of the exercise, which led to the exercise being conducted with latent collision risks.

### **3.2.2 Contributing Factors**

ACO was changed daily and lacked procedures and routes for transition between aerial refuelling and combat missions, and between combat missions and egress for the return to base.

The limited content in ACO and ATO resulted in the MC team obtaining an extensive workload.

The term SA was not clearly defined, which gave the participants scope for making different interpretations of, e.g. the altitude change procedure, ELEVATOR.

#### 4. SAFETY RECOMMENDATIONS

**The Swedish Armed Forces is recommended, in consultation with the Finnish and Norwegian armed forces, to:**

- Examine the need of clarifying the term SA (Situation Awareness) in the exercise rules contexts in which the term is used. *(RM 2018:03 R1)*
- Examine the need to address risks regarding administrative flight phases in connection with exercises and operations. *(RM 2018:03 R2)*
- Examine the need to conduct a simulation in order to validate the separation plan before the exercise. *(RM 2018:03 R3)*
- Evaluate the need and the possibilities to share recognized air picture with more participating units. *(RM 2018:03 R4)*

The Swedish Accident Investigation Authority respectfully requests to receive, at the **latest 19 June 2018**, information regarding measures taken in response to the safety recommendations included in this report.

On behalf of the Swedish Accident Investigation Authority,

Jonas Bäckstrand

Nicolas Seger