

Rachel Daeschler Head of Safety Intelligence & Performance Department Strategy & Safety Management Directorate

2014(D)53977 BBO/RSO/SM 1.2 Cologne, 10. SEP. 2014 Board of Accident Investogation (Statens Haverikommission / SHK) Mr. Hans Ytterberg Director General P.O. Box 12538 10229 Stockholm Sweden

Subject: Safety recommendations related to the event to BAE - JETSTREAM3100 registered ES-PJR, on 03/05/2013, at Sveg Airport - Sweden

Attachment: Safety recommendation reply

Dear Mr Ytterberg,

Following the Safety Recommendations mentioned above addressed to the European Aviation Safety Agency, please find thereafter the Agency's response.

Yours sincerely,

Rachel Daeschler





Subject: BAE - JETSTREAM3100 registered ES-PJR, on 03/05/2013, at Sveg Airport - Sweden

Reply to Safety Recommendation SWED-2014-003 received on 09/06/2014

Safety Recommendation:	EASA is recommended to endeavour to revise the emergency checklist for this aircraft type so that measures in the event of engine oscillations in connection with take-off are changed so as to be included as "memory items". (RL 2014:07 R2)
Response:	British Aerospace (BAe) Systems is in the process of revising the emergency checklist to make the existing checklist card (Erratic Engine Torque/EGT/RPM Indications), a memory item. EASA will continue to monitor progress through the Continuing Airworthiness (CAW) process under Part 21.
Status:	Open

2014(D)53977