

ACCIDENT

Aircraft Type and Registration:	Beech B55 Baron, SE-EXW	
No & Type of Engines:	2 Continental IO-470 piston engines	
Year of Manufacture:	1969	
Date & Time (UTC):	29 August 2016 at 0800 hrs	
Location:	Abbotsley (Rectory Farm) Airfield, Cambridgeshire	
Type of Flight:	Private	
Persons on Board:	Crew - 1	Passengers - None
Injuries:	Crew - None	Passengers - N/A
Nature of Damage:	Damage to left wingtip, right wing and fuselage	
Commander's Licence:	Private Pilot's Licence	
Commander's Age:	49 years	
Commander's Flying Experience:	573 hours (of which 22 were on type) Last 90 days - 21 hours Last 28 days - 7 hours	
Information Source:	Aircraft Accident Report Form submitted by the pilot	

During a flight from Belgium to Northern Ireland, the pilot reported a rudder restriction and made a precautionary landing at Rectory Farm Airfield. However, the pilot was unable to stop the aircraft within the runway length available causing substantial damage to the aircraft.