

Rachel Daeschler  
Head of Safety Intelligence & Performance Department  
Strategy & Safety Management Directorate

2014(D)53978  
BBO/RSO/SM1.2  
Cologne, 10. SEP. 2014

Board of Accident Investigation  
(Statens Haverikommission / SHK)  
**Mr. Hans Ytterberg**  
Director General  
P.O. Box 12538  
10229 Stockholm  
Sweden


**Subject:** Safety recommendations related to the event to BAE - JETSTREAM3100 registered ES-PJR, on 03/05/2013, at Sveg Airport - Sweden

Attachment: Safety recommendation reply

Dear Mr Ytterberg,

Following the Safety Recommendations mentioned above addressed to the European Aviation Safety Agency, please find thereafter the Agency's response.

Yours sincerely,



Rachel Daeschler

**Subject:** BAE - JETSTREAM3100 registered ES-PJR, on 03/05/2013, at Sveg Airport - Sweden

**Reply to Safety Recommendation SWED-2014-004 received on 09/06/2014**

<b>Safety Recommendation:</b>	EASA is recommended to take measures to ensure that initial and recurrent training on this aircraft type are supplemented with information and training regarding the risks of incorrect engine configurations during take-off. (RL 2014:07 R3)
<b>Response:</b>	EASA is considering the issue in question. The decision will depend on the emergency check-list revision, which is on-going.
<b>Status:</b>	Open

2014(D)53978